Determination of Eligibility under the National Historic Preservation Act: Architecture Details

Tulsa, Oklahoma

Topics

- NATIONAL REGISTER OF HISTORIC PLACES
  - CRITERIA FOR EVALUATION
    - HISTORIC CONTEXT
  - INTEGRITY

- COMPLETING THE “HISTORIC PRESERVATION RESOURCE ID FORM”

NATIONAL HISTORIC PRESERVATION ACT



National Historic Preservation Act of 1966, as amended

- 1992 - more involvement with Tribes
- 2001 - more responsibility for SHPOs to work directly with agencies
- 2004 - ACHP can initiate PAs with federal agencies without waiting for agency to act on their own initiative

- Response to demolition of historic resources

- Part of federal planning process

Section 106

What Actions are Subject to 106

- Easy to determine
  - Road construction
  - Waste water treatment plant construction
- Harder to determine
  - Dredging
  - New bank
  - Housing rehab

National Register of Historic Places

PROPERTIES ARE EVALUATED USING FOUR CRITERIA:

A. ASSOCIATION WITH EVENTS
B. ASSOCIATION WITH PERSONS
C. DESIGN CHARACTERISTICS
D. POTENTIAL TO YIELD INFORMATION

National Register of Historic Places

Criterion A

Properties that are associated with events that have made a significant contribution to the broad patterns of our history

National Register of Historic Places

Events

Can be a continuum of minor events.

For instance, “Commerce” is considered an event

National Register of Historic Places

Events

Ethnic Heritage-Black

Education

Social History

National Register of Historic Places

Criterion B

Property is associated with the lives of persons significant in our past

National Register of Historic Places

Persons

The person must be significant and there must be a direct tie to the property

National Register of Historic Places

CRITERION C

Property embodies the distinctive characteristics of a type, period, or method of construction or represents the work of a master, or possesses high artistic values, or represents a significant and distinguishable entity whose components lack distinction

National Register of Historic Places

Criterion C refers to the design characteristics

- Architectural styles
- Building types
- Construction methods
- Designer/creator

National Register of Historic Places

Criterion C

The most common Criterion used

Has many sub-categories under which to evaluate properties

National Register of Historic Places

Characteristics of a Period

May represent an example of an architectural style

National Register of Historic Places

National Register of Historic Places

Distinguishable entities whose components lack individual distinction

National Register of Historic Places

Historic Districts

National Register of Historic Places



National Register of Historic Places

National Register of Historic Places

National Register of Historic Places

CRITERION D

Property has yielded, or is likely to yield, information important in prehistory or history

National Register of Historic Places

Information Potential

National Register of Historic Places

All properties are evaluated within a context

- Temporal
- Geographic
- Resource type

National Register of Historic Places

National

State

Local

Local

State

National

National Register of Historic Places

1. Location
2. Design
3. Setting
4. Materials
5. Workmanship
6. Feeling
7. Association

Seven Aspects

Of

Integrity

National Register of Historic Places

National Register of Historic Places

National Register of Historic Places

National Register of Historic Places

Complete the Historic Preservation Resource Identification Form

- Location information is a must!
- Accurate dates of construction
- Clear placement map
- Follow instructions in manual

http://www.okhistory.org/shpo/106/rcmanual2014.pdf

National Register of Historic Places

National Register of Historic Places

Map


NE 21st St
State Museum of History
NE 21st St
N Walnut Ave
N Stiles Ave
NE 20th St
N Lindsay Ave
N Phillips Ave
NE 19th St
NE 19th St
A
NE 18th St
NE 18th St
NE 18th St
N Lincoln Blvd
NE 17th St
NE 17th St
N Lindsay Ave
Culbertson Dr
Harn Homestead
Culbertson Dr
East Dr
George's Happy Hog Barbeque
N Walnut Ave
NE 16th St
NE 16th St
NE 16th St

HISTORIC PRESERVATION RESOURCE IDENITIFICATION FORM

TYPE ALL ENTRIES:

1. PROPERTY NAME: WPA BUILDING
2. RESOURCE NAME: SAME
3. ADDRESS: BULL HOLLOW ROAD
4. CITY: BULL HOLLOW
5. VICINITY:
6. COUNTY: DELAWARE
7. COUNTY CODE: 041
8. LOT:
9. BLOCK:
10. PLAT NAME:
11. SECTION: 18
12. TOWNSHIP: T21N
13. RANGE: R23E

---

14. RESOURCE TYPE: B BUILDING
15. HISTORIC TYPE: 03C CIVIC
16. CURRENT FUNCTION: 03C CIVIC
17. AREA OF SIGNIFICANCE, PRIMARY: 030 ARCHITECTURE
18. AREA OF SIGNIFICANCE, SECONDARY:
19. DESCRIPTION OF SIGNIFICANCE: ELIGIBLE FOR NATIONAL REGISTER
20. DOCUMENTATION SOURCES: PERSONAL VISIT TO SITE

---

21. NAME OF PREPARER: ANDREA TAYLOR
22. THEMATIC SURVEY OF PROJECT: N PROJECT NAME:
23. DATE OF PREPARATION: 07/11/02
24. PHOTOGRAPHS: Y YEAR: 2002

JUL 17 2002
BY SHPO
RECEIVED
JUL 17 2002
BY SHPO

Revised 12/01/89

BUILDING CONSTRUCTION DESCRIPTION

25. ARCHITECT/BUILDER: UNKNOWN
26. YEAR BUILT: ~ 1930S
27. ORIGINAL SITE? Y DATE MOVED:
28. ACCESSIBLE? Y
29. ARCHITECTURAL STYLE: 81 NATIONAL FOLK
30. FOUNDATION MATERIAL: 98 INAPPLICABLE
31. ROOF TYPE: GABLE
32. ROOF MATERIAL: 22 SHINGLE
33. WALL MATERIAL, PRIMARY: 40 STONE
34. WALL MATERIAL, SECONDARY: 20 WOOD
35. WINDOW TYPE: 1/1 HUNG
36. WINDOW MATERIAL: 20 WOOD
37. DOOR TYPE: SOLID
38. DOOR MATERIAL: 20 WOOD
39. EXTERIOR FEATURES: 1 STORY W/PORCH & THREE CHIMNEYS
40. INTERIOR FEATURES:
41. DECORATIVE DETAILS:
42. CONDITION OF RESOURCE: 04 POOR
43. DESCRIPTION OF RESOURCE (Present and Historic):

1 STORY W/ GABLED ROOF AND A PORCH & THREE CHIMNEYS

44. COMMENTS:

45. PLACEMENT:

NAME OF PROPERTY: WPA BUILDING
LOCATION: DELAWARE COUNTY
BULL HOLLOW
OKLAHOMA
BULL HOLLOW ROAD
NAME OF PHOTOGRAPHER: ANDREA TAYLOR
DATE OF PHOTOGRAPH: 07/10/02
LOCATION OF NEGATIVE: ENVIRONMENTAL
PROTECTION OFFICE
INDICATION OF DIR. CAMERA IS POINTING: EAST
NUMBER OF PHOTOGRAPH IN SERIES: 3 OF 3

NAME OF PROPERTY: WPA BUILDING
LOCATION: DELAWARE COUNTY
BULL HOLLOW
OKLAHOMA
BULL HOLLOW ROAD
NAME OF PHOTOGRAPHER: ANDREA TAYLOR
DATE OF PHOTOGRAPH: 07/10/02
LOCATION OF NEGATIVE: ENVIRONMENTAL
PROTECTION OFFICE
INDICATION OF DIR. CAMERA IS POINTING: NORTH
NUMBER OF PHOTOGRAPH IN SERIES: 2 OF 3

OPINION?

- Eligible
  - Criterion A – Association with New Deal work relief program (WPA) in Delaware County

MORE COMMONLY, WE REVIEW…

HPRID Form

Styles

- Bungalow/Craftsman
- National Folk
- Tudor Revival
- Prairie School
- Colonial Revival
- Modern Movement
- Mission/Spanish Revival
- Shotgun
- Art-Deco
- Moderne
- Commercial

National Folk

Colonial Revival

Tudor Revival

Mission/Spanish Revival

Prairie School

Bungalow/Craftsman

Art Deco

Moderne

Modern Movement

Shotgun

Commercial

Foundations

Concrete

Granite

Brick

Stucco

Stone

Sandstone

Roof Type

Front Gable

Side Gable

Cross Gable



Hipped



Hipped Gable



Pyramid



Gambrel



Flat

Hip with Gablet





Shed





Mansard





Roof Material

Asphalt



Asphalt

Tin

Terra Cotta

Asbestos

Slate

Ceramic Tile

Wood

Shingle

Metal



Tar/Felt/Gravel

Wall Material

Wood


Saddle
Square
V-notched
Half-dovetail
Full-dovetail


CLAPBOARD
WEATHERBOARD
BEVEL
SHIPLAP
BOARD & BATTEN

Wood



Brick



Sandstone

Synthetics

Weatherboard



Vinyl Siding

Metal

Asbestos

Granite

Stone

Stucco

Shake

Wood Shingle

Concrete

Window Type

Casement



Fixed

Slide

Awning



Hopper

Hung

Window Material

Window Material:

Does not refer to storm windows!!!!!!!!!!!!!!

Wood

Vinyl

Aluminum

Door Type

Slab

Glazed



Paneled

Door Material

Wood

Metal

Condition of Resource

Excellent

Good

Fair

Poor

Ruins

Questions???

Specifics on viewsheds

Examples

Example of Project

USDA:

Western Farmers Electric Cooperative Proposed Bear Creek Substation and Tap Line Project



Elig
Cit. A
Education
LSO
9/28/15

HISTORIC PRESERVATION RESOURCE IDENTIFICATION FORM

PLEASE ENTER ALL DATA IN UPPERCASE

1. PROPERTY NAME: PROPERTY 1
2. RESOURCE NAME: COMMUNITY CENTER/SCHOOL NO. 106
3. ADDRESS: NW CORNER INTERSECTION OF E RIVER RD & N 106 LN
4. CITY: NEWKIRK 4. VICINITY: YES
6. COUNTY NAME: KAY
7. LOT: 8. BLOCK: 9. PLAT NAME:
10. SECTION: 20, SE/SE/SE/SE 11. TOWNSHIP: 28 NORTH 12. RANGE: 4 EAST
13. LATITUDE (NORTH): (ENTER AS: "dd.ddddd")
14. LONGITUDE (WEST): (ENTER AS: "-dd.ddddd")
15. UTM ZONE: 14 16. NORTHINGS: 4084048 17. EASTINGS: 688239
18. RESOURCE TYPE: BUILDING
19. HISTORIC FUNCTION: SCHOOL
20. CURRENT FUNCTION: MEETING HALL
21. AREA OF SIGNIFICANCE, PRIMARY: EDUCATION
22. AREA OF SIGNIFICANCE, SECONDARY: COMMUNITY PLANNING AND DEVELOPMENT
23. DESCRIPTION OF SIGNIFICANCE: RURAL SCHOOLS PREDATING LATE 20TH CENTURY CONSOLIDATIONS
24. DOCUMENTATION RESOURCE:
25. NAME OF PREPARER: DON L DYCUS, MA, RPA
59. SURVEY PROJECT YES 26. PROJECT NAME: HARDY TO BEAR CREEK SUBSTATION & TAP LINE
27. DATE OF PREPARATION: 09/18/2015 28. PHOTOGRAPHS 2 COLOR
29. YEAR: 2015

RECEIVED
SEP 24 2015
SHPO

30. ARCHITECT/BUILDER: NO DATA

31. YEAR BUILT: NO DATA

32. ORIGINAL SITE: NO DATA

33. DATE MOVED:

34. FROM WHERE:

35. ACCESSIBLE:

36. ARCHITECTURAL STYLE: NATIONAL FOLK

37. OTHER ARCHITECTURAL STYLE:

38. FOUNDATION MATERIAL: CONCRETE

39. ROOF TYPE: SIDE-GABLE

40. ROOF MATERIAL: METAL

41. WALL MATERIAL, PRIMARY: BRICK

42. WALL MATERIAL, SECONDARY:

43. WINDOW TYPE: DOUBLE-HUNG

44. WINDOW MATERIAL: WOOD

45. DOOR TYPE: DOUBLE-SLAB

46. DOOR MATERIAL: WOOD

47. EXTERIOR FEATURES: GABLED SIDE WING EXTENSION & VESTIBULE ENTRY

48. INTERIOR FEATURES: NO DATA

49. DECORATIVE DETAILS:

50. CONDITION OF RESOURCE: FAIR (SOMEWHAT IN NEED OF MAINTENANCE)

51. DESCRIPTION OF RESOURCE: SINGLE-STORY WOODFRAMED FORMER SCHOOLHOUSE WITH EXTENDED GABLED VESITBULE FRONT ENTRY, GABLED SIDE WING EXTENSION, BRICK FACADE, DOUBLE-HUNG WOOD SASH WINDOWS, UPDATED CHANNELED METAL ROOF.

52. COMMENTS: PROPERTY WOULD BE PARTIALLY SCREENED FROM POTENTIAL EFFECTS OF PROJECT BY EXISTING WINDROW TO SOUTHEAST

53. ATTACH LOCATION MAP

54. LISTED ON NATIONAL REGISTER: NO DATA

55. CONTINUATION

PROPERTY 1. Kaw City NW, Okla.-Kans., 1976 USGS 7.5' topographic quadrangle



Property 1, SE/SE/SE/SE Sec. 20-28N-4E. TOP FRAME: SE corner elevation, view northwest. MIDDLE FRAME: SW corner elevation, view northeast. BOTTOM FRAME: NE corner elevation, view southwest. (08/23/2015, D.L. Dycus)


NRHP eligible school
N 106th Ln
N 106th Ln
E0090 Rd
E0090 Rd
East River Rd
East River Rd
S 106th Ln
S 106th Ln
Substation Location

What happened 4 May 1970?

Kent State Massacre


Location Map May 4- Shooting
ALLISON KRAUSE
PRENTICE HALL
DONALD MacKENZIE
ALAN CANFORA
TAYLOR HALL
SECOND PARKING LOT
BULLET HOLE IN PRENTICE HALL DORMITORY WINDOW
TOM GRACE
VICTORY BELL
SANDY SCHEUER
PARKING LOT
JEFFREY MILLER
ROBERT STAMPS
DOUG WRENTMORE
JOHN CLEARY
TWO BULLET HOLES IN TREE
DEAN KAHLER
JOSEPH LEWIS
BULLET HOLE IN STATUE
6 GUARD HEADED BACK UP HILL– STUDENTS FOLLOW
GUARD ASSUMED FIRING POSITIONS BUT, DID NOT FIRE 5
7 GUARD WHEELED AND FIRED
WILLIAM SCHROEDER
PAGODA
JAMES RUSSELL
GUARD CIRCLED TO PRACTICE FIELD
ADVANCED
ER HILL
STUDENTS 4
Dick MAYER

Figure 23. The Guard reestablished on the Commons surrounding the ROTC building with students to the north and south, May 4, 1970, facing south.

Allison Krause
PEACE