

WPA RESOURCES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

CUSTER COUNTY

(Region 7)

	<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1.	Fire Station ✓	523 Choctaw	Clinton	7CUS5a,b
2.	Auction Building ✓	6th & Nowahy	Clinton	7CUS6a,b
3.	Livestock Bldg. ✓	6th Street	Clinton	7CUS7a-c
4.	Amphitheater ✓	6th and Opal	Clinton	7CUS8a,b
5.	Nat. Guard Armory ✓	13th and Opal	Clinton	7CUS11a,b
6.	Athletic Field/Wall ✓	S. 13th & Hays	Clinton	7CUS12a,b
7.	Community Bldg. ✓	Custer City Rd.	Custer City	7CUS14a,b
8.	Nat. Guard Armory ✓	8th & Rainey	Weatherford	7CUS18a,b
9.	Southwestern State			
	College Rec. Bldg. ✓	Broadway	Weatherford	7CUS19a,b
10.	Southwestern State			
	Recreation Bldg. ✓	Broadway	Weatherford	7CUS20a,b
11.	Pool & Bathhouse ✓	Huber & Indiana	Weatherford	7CUS21a,b
12.	Milam Stadium ✓	7th and College	Weatherford	7CUS22a,b
13.	SWOSU Chapel ✓	Custer Street	Weatherford	7CUS24a,b
14.	Shop Building ✓	State Street	Weatherford	7CUS25a-c
15.	Jefferson School ✓	T14N, R14W, NE16	Thomas vic	7CUS17a-c

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Clinton Fire Station
2. PROPERTY ADDRESS Street Address: 523 Choctaw
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: 13 & 14 Township: 12N
Block or Section: Block 26, Original Townsite Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: Fixed: Pivotal: x
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double: Overhead
Other, specify: Glass panel
Decorative features: sidelights

22. LARGE EXTERIOR FEATURI

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Wood doors on the west are not original equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and firemen

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS5a,5b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$6,895

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Auction Building
2. PROPERTY ADDRESS Street Address: 6th and Nowahy Streets
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Tract NE quarter Township: 12N
Block or Section: Section 14, NE quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: x Government: Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: x Religious: Other: Playhouse & Theater
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: Single: Double: x
Other, specify: Sidelights and glass doors
Decorative features: Frosted glass doors

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
There are no windows in the building; the fron doors are newly installed feature as well as the sidelights.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS6a,6b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$31,795

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this appropriation was a Livestock Exhibit building that is reported on a separate report form because of its vastly different structure, condition, and location. The building reported in this report is presently housing the Southwest Playhouse.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Livestock Exhibit Building
2. PROPERTY ADDRESS Street Address: 6th Street
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 14, NE Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: x Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: x Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Pre-school
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double: Overhead
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows, except those on the west side, have been boarded up.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS7a-7c Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$84,778

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This building and the Auction Building are the two structures remaining of the old fair grounds site. It is apparent that as the other buildings were razed, the land was sold.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Ampitheater
2. PROPERTY ADDRESS Street Address: 6th and Opal Streets
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Township: 12N
Block or Section: Section 23,NW Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: x Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Fine Arts performances
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: Half-domed stage

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: The bleacher seats are arranged in tiers and spread out into a fan shaped theater. The stage is surrounded by a half dome.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS8a,8b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$2,187

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This structure is the most impressive feature of the park which is called McLain-Rogers Park.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Clinton Armory
2. PROPERTY ADDRESS Street Address: 13th & Opal Streets
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: 17-20 Township: 12N
Block or Section: Block 8, Lancaster Addition Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: x Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: x Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: 1 Partial: 1 Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecting joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS11a,11b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$51,710

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this appropriation are funds designated for additional housing. This housing facility could not be located.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Clinton School Athletic Field and Wall
2. PROPERTY ADDRESS Street Address: S.13th & Hays Streets
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 14, SW Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object: x
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: Type Brick: Stone: x Type: Red
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS12a,12b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$10,048

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The school was razed because of advanced deterioration and the athletic field was given over to public use and now serves as the Little League field for Clinton.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Custer City Community Building
2. PROPERTY ADDRESS Street Address: Custer City Road
City: Custer City County: Custer
State: OK Zip Code: 73639 Region: 7
3. PROPERTY LOCATION Lot: 7-12 Township: 14N
Block or Section: Block 38 Range: 16W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: Pivotal: x
Hopper: Other: .
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Railing to front door is not original equipmwnt.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and Frank Bach, City Treasurer.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS14a,14b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,910

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Weatherford Armory
2. PROPERTY ADDRESS Street Address: 8th & Rainey Ave.
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: tract Township: 12N
Block or Section: Block 62, Original townsite Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial: .
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: x Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: x Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: x Single: x Double: x
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
The four overhead doors on the west side are not original equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS18a,18b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$41,298

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this appropriation were extra housing facilities which could not be located.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: SW State Shops and Recreation Building
2. PROPERTY ADDRESS Street Address: Broadway
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: unknown Township: 12N
Block or Section: Section 8 Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: x Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: 1 Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Shop windows have been boarded up; windows at ground level, on north side, have been boarded up.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS19a,19b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,201

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This building was originally on the site of Southwestern State Teachers College. It is presently owned and used by the city school system.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: SW College Recreation Building
2. PROPERTY ADDRESS Street Address: Broadway
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: unknown Township: 12N
Block or Section: Section 8 Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain: x
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: 1 Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: Fixed: Pivotal: x
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other: '
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: x Gables:
Verandas: Chimneys: x placement/material: end wall stone
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
End wall chimney is not an original feature; AC units added features.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS20a,20b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$49,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This structure is a split-level building. There is a sandstone wall that lines the stairs leading to the lower level. If this building is a WPA project erected for SW Teachers College, it is presently owned and used by the city school system.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: City Swimming Pool and Bathhouse (Means Pool)
2. PROPERTY ADDRESS Street Address: Huber & Indiana Streets'
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: 1-24 Township: 12N
Block or Section: Block 22, Huber Addition Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: x Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Metal louvers cover the front windows.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS21a,21b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$27,120

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Milam Stadium Grandstand
2. PROPERTY ADDRESS Street Address: 7th and College Streets
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 8NW Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: College campus
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower:	projecting:	joined:	other:	
Entries:	Pedimented:	Porte Cochere:	Other:	
Porches:	Entry:	Full Width:	Wrap-around:	Other:
Stairs:	Balconies:	Dormers:	Gables:	
Verandas:	Chimneys:	placement/material:		
Other:				

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS22a,22b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$31,103

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The structure is concrete bleacher seats supported by steel girders.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: SWOSU Chapel
2. PROPERTY ADDRESS Street Address: Custer Street
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 8 Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: College campus
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Wood shingle
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: x Gables:
Verandas: Chimneys: x placement/material: end wall sandstone
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: front door is replacement; windows may be historic equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS24a,24b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$3,889

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The building presently houses the campus Health Center.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Shop Building
2. PROPERTY ADDRESS Street Address: State Street
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 8NW Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: College campus
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other: Cross Gabled
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: x Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables: x
Verandas: Chimneys: x placement/material: end wall sandstone
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
End wall chimney is not original feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS25a-25c Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$20,718

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: A sandstone wall surrounds the site of this structure and was a part of the project.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Jefferson School and coal house
2. PROPERTY ADDRESS Street Address: Section 16NE; 14N; 14W
City: Thomas (vic) County: Custer
State: OK Zip Code: 73669 Region: 7
3. PROPERTY LOCATION Lot: Township: 14N
Block or Section: Section 16NE Range: 14W
4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes (School only)
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other: .
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No: Fixed: x Pivotal:
Casement: x Sliding: Other:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: x Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: x Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: x No:
Other: Coal House

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Transom has been boarded up; Front and south windows have combination storm windows mounted. The structure connecting the school with the coal house is not a part of this project.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS17a-17c Date taken: May 18, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$6,606

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

CUSTER COUNTY

(Region 7)

<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1. Arapaho Com. Bldg ✓	Main and Broadway	Arapaho	7CUS1a,b
2. McClain-Rogers Pk. ✓	11th & Opal	Clinton	7CUS9a-d
3. City Park Restrooms ✓	11th & Opal	Clinton	7CUS10a,b
4. Heating and Laundry Facility ✓	T12N, R17W, NE26	Clinton	7CUS13a,b
5. Com. Bldg. and Add ✓	120 E. Broadway	Thomas	7CUS15a-d
6. Bus Garage & Shop ✓	920 E. Main	Thomas	7CUS16a-c
7. Miliam Stadium Field House ✓	7th & College	Weatherford	7CUS23a,b
8. Elementary School and Addition ✓	Wachholtz Street	Butler vic	7CUS2a-c
9. Gyp Hill School ✓	T12N, R15W, SE8	Weatherford vic	7CUS26a,b
10. Pie Flat School ✓	T13N, R19W, NW2	Butler vic	7CUS3a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Arapaho Community Building
2. PROPERTY ADDRESS Street Address: Main Street & Broadway
City: Arapaho County: Custer
State: OK Zip Code: 73620 Region: 7
3. PROPERTY LOCATION Lot: 20 Township: 13N
Block or Section: Block 32 Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: .
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type: Stucco
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows, except the two in the front, have been filled in; the lean-to addition is not original; the door opening on the west side has been filled in.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and life-long resident.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS1a,1b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$4,874

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The alterations that have been made to the building are extreme enough to disqualify the site for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: McLain-Rogers Park
2. PROPERTY ADDRESS Street Address: 11th and Opal Streets
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Township: 12N
Block or Section: Section 23, NW Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site: x
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projected joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS9a-9d Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$50,797

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: There are various structures remaining throughout the park, such as picnic tables, drainage creeks, and a perimeter wall.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: City Park Public Restrooms
2. PROPERTY ADDRESS Street Address: 11th and Opal Street
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Township: 12N
Block or Section: Section 23, NW Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal: x
Government: Religious: Other: Girl Scout Office
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
The front door has a screen door that is additional equipment; there is a large addition at the rear of the building. This addition is faced with a different kind of sandstone, but it blends fairly well..

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS10a,10b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$3,739

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The alterations to the property have been severe enough to disqualify the site for further study. Previous to Girl Scout occupancy, the building served as the office for the Highway Patrol.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Heating Plant and Laundry Facility
2. PROPERTY ADDRESS Street Address: Section 26NE
City: Clinton County: Custer
State: OK Zip Code: 73601 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 26, NE Quatrant Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: Hospital compound
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Sanitorium Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Hospital
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: 1 Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: x
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Free standing stack
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS13a,13b Date taken: My 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$111,643

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: There was no evidence that the building also housed the heating plant. This structure is presently used as the laundry facility for the Oklahoma Veterans Hospital.

Figure "D":

1. PROPERTY NAME: Thomas Community Building and addition
2. PROPERTY ADDRESS Street Address: 120 E. Broadway
City: Thomas County: Custer
State: OK Zip Code: 73669 Region: 7
3. PROPERTY LOCATION Lot: 3-5 Township: 14N
Block or Section: Block 98 Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: B.W.Nolen Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Natural
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: x Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Combination storm door mounted on single entrance in the front; Steel fire doors, without exterior access, replaced side entrance doors.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and retired Superintendent of Schools. Another source was Mr. Webb, life long resident.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS15a-15d Date taken: May 18, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$38,681

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: According to the town historian, Mr. Webb, an addition was constructed in order to house a library and a jail facility. The bars from the jail windows have subsequently been removed.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Thomas School Bus Garage and Shop
2. PROPERTY ADDRESS Street Address: 920 N. Main
City: Thomas County: Custer
State: OK Zip Code: 73669 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 14N
Block or Section: Blocks 1,2,6 Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor: ,
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Altering process
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: x Full: 1 Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Wood Shake
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower:	projecting:	joined:	other:	
Entries:	Pedimented:	Porte Cochere:	Other:	
Porches:	Entry:	Full Width:	Wrap-around:	Other:
Stairs:	Balconies:	Dormers:	Gables:	
Verandas:	Chimneys:	placement/material:		
Other:				

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Overhead door is not original equipment and has been installed in a different location than original overhead door.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report, Alvin Beadles, FFA instructor, and Jin Litsch, High School Principal.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS16a-16c Date taken: May 18, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$3,599

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Included in this project was an wall around an oval driveway. This is included in the photographs.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Milam Stadium Field House
2. PROPERTY ADDRESS Street Address: 7th & College Streets
City: Weatherford County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: Tract Township: 12N
Block or Section: Section 8NW Range: 14W
4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: College campus
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Front door is not original equipment; east half of the building is an addition; doors on west side are replacements.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: etype:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS23a,23b Date taken: May23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$6,462

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The extensive alterations to the building disqualify the structure for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Butler Elementary Public School and Addition.
2. PROPERTY ADDRESS Street Address: Wachholtz Street
City: Butler (vic) County: Custer
State: OK Zip Code: 73625 Region: 7
3. PROPERTY LOCATION Lot: Township: 13N
Block or Section: Section 4NE Range: 19W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground: x
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURI

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS2a-2c Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$55,810

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The storm cellar is the only remaining structure on the site. The school burned down in 1960 and the debris was removed.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Gyp Hill Public School
2. PROPERTY ADDRESS Street Address: Section 8SE; 12N; 15W
City: Weatherford (vic) County: Custer
State: OK Zip Code: 73096 Region: 7
3. PROPERTY LOCATION Lot: Township: 12N
Block or Section: Section 8SE Range: 15W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other: Rural
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private use
Commercial: x Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other: Cross gable
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Transom is boarded up; rear wall is stucco and rear portion of the structure is inaccessible; metal lean-to on the west side is not an original feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS26a,26b Date taken: May 23, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$4,885

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The building is presently used as a small business enterprise - a dog grooming studio.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Pie Flat School
 2. PROPERTY ADDRESS Street Address: Section 2NW;13N;19W
City: Butler (vic) County: Custer
State: OK Zip Code: 73625 Region: 7
 3. PROPERTY LOCATION Lot: Township: 13N
Block or Section: Section 2NW Range: 19W
 4. PROPERTY TYPE (Category)
Building: x Object:
Structure: x Site:
 5. PLACEMENT ON BLOCK or MAP
 6. Identification uncertain:
 7. Unable to locate:
 8. Warrant further study National Register: No
 9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
 10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
 11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
 12. ORIGINAL SITE Yes: x No: Date moved and from where:
 13. ARCHITECT/BUILDER: Year Built: 1939
 14. ACCESSIBLE Yes: No: x
 15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Abandoned
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
 17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
 18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
 19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
 20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
 21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7CUS3a,3b Date taken: May 24, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 14, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$23,090

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: All that is left of the school building is in ruin, but the storm cellar is still in place. Because the site was inaccessible, determining the structural features of the building was impossible.