

WPA RESOURCES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

DEWEY COUNTY

(Region 7)

	<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1.	Carmargo School ✓	3rd & Field	Carmargo	7DEW1a,b
2.	Fay School & Aud. ✓	East 3rd St.	Fay	7DEW4a-c
3.	Leedey Public School ✓	6th & Samson	Leedey	7DEW5a-d
4.	Seiling School Bus Barn and Shop ✓	101 Elm	Seiling	7DEW8a,b
5.	Vici City Hall ✓	Main Street	Vici	7DEW11a,b
6.	Vici Public School ✓	3rd and Miller	Vici	7DEW10a-c

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Camargo Public School
2. PROPERTY ADDRESS Street Address: Third & Field Streets
City: Camargo County: Dewey
State: OK Zip Code: 73835 Region: 7
3. PROPERTY LOCATION Lot: 1-24 Township: 18N
Block or Section: Block 35 Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: x
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: c
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe: Stucco
20. WINDOWS Historic, Wooden: Metal: Present: Metal
Window type Hung: Single: Double: Triple:
Transoms Yes: x No: Pivotal:
Casement: x Sliding: Fixed: x
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: x Entry: Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Transom over door has been boarded over; the entrance in photo is on the north end; windows on west side are painted over with blue paint.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey and Superintendent of Carmargo school.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW1a,1b Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: \$15,094

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The door that is in photo is actually the original back door. The front was removed when addition was added in 1955. The post-WPA additions have been tastefully done.

Attachment :

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Fay Auditorium and School
2. PROPERTY ADDRESS Street Address: Third Street
City: Fay County: Dewey
State: OK Zip Code: 73646 Region: 7
3. PROPERTY LOCATION Lot: Township: 16N
Block or Section: Section 35SE Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Steel Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: x Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Downspouts have been added; roof over front entrance added in 1948; the school west of the gym was erected in 1948 when original school was razed. exterior stone has been whitewashed many times.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW4a-4c Date taken: May 18, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$30,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: School and auditorium function primarily as a community center but Thomas Board of Education maintains the school and the grounds.

HISTORIC PRESERVATION SURVEY INVENTORY FORM: -

Figure "D":

1. PROPERTY NAME: Leedey Public School
2. PROPERTY ADDRESS Street Address: 6th & Samson
City: Leedey County: Dewey
State: OK Zip Code: 73654 Region: 7
3. PROPERTY LOCATION Lot: 1-24 Township: 16N
Block or Section: Block28, Section 17NE Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Forrest Butler, Architect Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Brick Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Metal
Window type Hung: x Single: x Double: Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projected joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: x Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows and doors have been replaced since original construction. All are now aluminum sash installed about 1955. Transoms are covered over with wood panels.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and Mr. Velharticky, Superintendent of Leedey schools.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW5a-5d Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg. DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$35,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

ITEM 13: Ellis Nichols & Cramer, contractors.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Seiling Public School Bus Garage and Shop
2. PROPERTY ADDRESS Street Address: 101 Elm
City: Seiling County: Dewey
State: OK Zip Code: 73663 Region: 7
3. PROPERTY LOCATION Lot: Township: 19N
Block or Section: Section 4SW Range: 16W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other: Mason block
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: Stucco
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present: x
Window type Hung: x Single: x Double: Triple:
Transoms Yes: No: x
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: Metal
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Awning over west entrance is added feature. The chimneys below the roof line have been removed and only the metal flanges on the roof remain.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey report and Mr. Dougherty, Superintendent of Seiling schools.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW8a,8b Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$3,713

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The structure is presently serving as the school maintenance building.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: City Offices and Senior Citizens Center
2. PROPERTY ADDRESS Street Address: Main Street
City: Vici County: Dewey
State: OK Zip Code: 73859 Region: 7
3. PROPERTY LOCATION Lot: 15-18 Township: 19N
Block or Section: Block 36; Section 2 Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal: x
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: 1 Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: semi-barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present: x
Window type Hung: x Single: x Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir joined: other:
Entries: Pedimented: Porte Cochere: Other: Stoop
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material: Brick End-Wall
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All original doors have been replaced;Awning over fron entry is post-WPA;
Front stairs of reinforced concrete is not original feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey Report and Town Clerk

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW11a,11b Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: \$17,794

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Vici Public School
2. PROPERTY ADDRESS Street Address: 3rd & Miller
City: Vici County: Dewey
State: OK Zip Code: 73859 Region: 7
3. PROPERTY LOCATION Lot: 1-24;1-12 Township: 19N
Block or Section: Blocks 15 & 18;Section 2 Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: X
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: x Double: Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: x Present:
Style: Glass panel Wood: Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir joined: other:
Entries: x Pedimented: Porte Cochere: Other: Stoop
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Brick extensiion on front entrance is post-WPA; all upper halves of windows have been boarded up; there is a gymnasium addition that was also WPA.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey Report and Superintendent of Vici public schools.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW10a-10c Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$20,535

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The gymnasium can be seen only from the interior. It is at right angles and it helps form an inner court yard. Photo 11c documents its existence.

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

DEWEY COUNTY

(Region 7)

	<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1.	Municipal Waterworks/	North Main St.	Camargo	7DEW2a,b
2.	City Park/	North Main St.	Leedey	7DEW6a
3.	Oakwood School /	East Oak St.	Oakwood	7DEW7a-d
4.	County Courthouse Add./	Broadway St.	Taloga	7DEW9a,b
5.	"CON" 6 School/	T18N, R20W, NE18	Canton vic	7DEW3a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Municipal Waterworks
2. PROPERTY ADDRESS Street Address: Sections 24NE & 30SE, 18N, 20W
City: Camargo County: Dewey
State: OK Zip Code: 73835 Region: 7
3. PROPERTY LOCATION Lot: Township: 18N
Block or Section: Sections 24NE & 30SE Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other: Steel
18. ROOFING MATERIAL Historic: Composition Present:
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Brick Present:
Masonry, bearing: Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower:	projecting:	joined:	other:	
Entries:	Pedimented:	Porte Cochere:	Other:	
Porches:	Entry:	Full Width:	Wrap-around:	Other:
Stairs:	Balconies:	Dormers:	Gables:	
Verandas:	Chimneys:	placement/material:		
Other:				

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: WPA Field survey and Mr. Ward, Mayor of Camargo

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW2a,2b Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,435

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This facility is abandoned and no longer in use. This project replaced a system of windmills. Originally there were five wells and five storage tanks, but just one of each structure remains in tact. Each well had a structure built around it.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: City Park
2. PROPERTY ADDRESS Street Address: Main Street
City: Leedey County: Dewey
State: OK Zip Code: 73654 Region: 7
3. PROPERTY LOCATION Lot: 1-24 Township: 16N
Block or Section: Block 9, Section 17 Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW6a Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$9,619

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The only structure remaining is an oval that is filled with dirt and is used as a flower bed. This may be the wading pool!

Attachment :

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Oakwood School & Addition
2. PROPERTY ADDRESS Street Address: Oak Street
City: Oakwood County: Dewey
State: OK Zip Code: 73658 Region: 7
3. PROPERTY LOCATION Lot: 1-8 Township: 17N
Block or Section: Block 5, Section 21SW Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: Stucco
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present: Metal
Window type Hung: x Single: x Double: Triple:
Transoms Yes: x No:
Casement: x Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Wood Present: Wood
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecti _ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type: large shed
Work: Storage sheds, matches primary building Yes: No: x
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and life-long resident, the owner of the feed store.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW7a-7d Date taken: May 19, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$67,077

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: There was a shop addition included in this project. The structure burned and was abandoned because the fire gutted it. It still stands but is in total ruin.
The addition that is attached to the original school is still in use as a community building. It is maintained by Oakwood residents and is used as a cafeteria for the community center. The facility is leased by the community on a 99-year lease.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Dewey County Courthouse
2. PROPERTY ADDRESS Street Address: Broadway
City: Taloga County: Dewey
State: OK Zip Code: 73667 Region: 7
3. PROPERTY LOCATION Lot: Township: 18N
Block or Section: Block 83, Section 13NE Range: 16W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 3 Full: 2 Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Stucco Present: Stucco
Masonry, bearing: x Type Brick: Stone: x Type:
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: x Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: Combination aluminum storms and screens have been added; rear entrance is not original equipment; rear entrance doors are added features.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and County Clerk, Pat Riley.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW9a,9b Date taken: May 20, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$20,596

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The addition is at the rear of the courthouse and added 18 offices to the building.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: "CON" 6 School
2. PROPERTY ADDRESS Street Address: Section 18NE, 18N, 14W
City: Canton (near) County: Dewey
State: OK Zip Code: 73724 Region: 7
3. PROPERTY LOCATION Lot: Township: 18N
Block or Section: Section 18NE Range: 14W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Abandoned
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Brick Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: x Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: x Present:
Style: Wood: Metal: Single: Double:
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: Windows are covered over with corrugated tin; door openings are either "open" or covered over with corrugated tin

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey Report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7DEW3a,3b Date taken: May 18, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 7, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$23,856

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Building is abandoned, but someone uses it to store farm equipment. The huge opening in the front was access to the gymnasium which has a barrel roof that is hidden by the exterior walls. Cannot see evidence that this opening was actually for transom doors. The property is under the jurisdiction of the Canton School District which is located in Blaine County.