

WPA PROPERTIES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

HARMON COUNTY


(Region 7)

	<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1.	Community Building /	Kennedy & Olney	Gould	7HAR1a,b
2.	High School & Gym /	T2N, R24W, NW7	Gould	7HAR3a,b
3.	Junior High School /	T2N, R24W, NW7	Gould	7HAR4a,b
4.	School Truck Shed/Shop /	T2N, R24W, NW7	Gould	7HAR2a,b
5.	City Hall /	106 W. Jones	Hollis	7HAR6a,b
6.	Community Building /	511 N. Morton	Hollis	7HAR8a,b
7.	Will Husband Stadium /	E. Walnut	Hollis	7HAR9a,b
8.	Home Ec. and Voc. Ed. Building /	East Street	Vinson	7HAR11a,b
9.	Goodwill School /	T3N, R24W, NE2	Duke vic	7HAR14a,b
10.	Goodwill Sch. Bus Barn /	T3N, R24W, NE2	Duke vic	7HAR15a,b
11.	Arnett School /	T3N, R26W, NW8	Hollis vic	7HAR16a,b
12.	Arnett School Bus Barn /	T3N, R26W, NW8	Hollis vic	7HAR17a,b
13.	Arnett Teacherage /	T3N, R26W, NW8	Hollis vic	7HAR18a,b
14.	Westview Garage & Home Ed. Building /	T3N, R26W, SW31	Hollis vic	7HAR19a,b
15.	Westview School Gym /	T3N, R26W, SW31	Hollis vic	7HAR20a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Gould Community Building
2. PROPERTY ADDRESS Street Address: Kennedy and Olney St.
City: Gould County: Harmon
State: OK Zip Code: 73544 Region: 7
3. PROPERTY LOCATION Lot: 1-6 Township: 3N
Block or Section: 14, Gould Original Range: 25W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1937-38
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal: x
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: x Type Brick: Stone: x Type: Native
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present: Same
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features: Sidelights:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: Use of large and small randomly laid stone.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Various windows boarded over; Concrete stucco covers the east and north walls; new wooden doors.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR-1a,1b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne

DATE: 6/25/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$8,000


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Gould High Sch. and Gym
2. PROPERTY ADDRESS Street Address:
City: Gould County: Harmon
State: OK Zip Code: 73544 Region: 7
3. PROPERTY LOCATION Lot: Township: 2N
Block or Section: NW7 Range: 24W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Otto Payton-Con. Supt. Year Built: 1936-37
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: x Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Bowed
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Glass Panel Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: Concrete capping on parapet; Rusticated Brickwork.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: New metal glass-panel doors; window panes are painted blue; small concrete block addition to the east side.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR3a,3b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/25/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$86,759

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.


ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Gould Jr. High Sch.
2. PROPERTY ADDRESS Street Address:
City: Gould County: Harmon
State: OK Zip Code: 73544 Region: 7
3. PROPERTY LOCATION Lot: Township: 2N
Block or Section: NW7 Range: 24W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:

6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes



9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:

10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936

14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Metal
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:

21. DOORS Material and type. Historic: Present: x
Style: Glass Panel Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: Porte Cochere: Other: Arched, recessed
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: stoop

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:
Windows painted blue; new double glass-panel doors; concrete block addition to east side; door on east side boarded over.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7Har4a,4b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/25/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$11,351


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Gould Sch. Truck Shed and Workshop
2. PROPERTY ADDRESS Street Address:
City: Gould County: Harmon
State: OK Zip Code: 73544 Region: 7
3. PROPERTY LOCATION Lot: Township: 2N
Block or Section: NW7 Range: 24W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: x Type Brick: Stone: x Type: Native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects: Brick Sills
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: Arches on
parapets.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include
dates, work done and effect. Continue on additional sheets if needed: Tin
addition to east end; Window openings filled with concrete block.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important
example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are
NOT acceptable.

Number: 7HAR-2a,2b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/25/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$8,815

*NOTE. To continue any item, list by item number and title. Attach
additional, full sheets if needed.

ADDITIONAL COMMENTS:

Attachment :

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Hollis City Hall and County Jail
2. PROPERTY ADDRESS Street Address: 106 W. Jones
City: Hollis County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: 1-6 Township:
Block or Section: Block 2, Hollis Original Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: Native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: wood sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: glass panel Wood: Metal: x Single: x Double: x
Other, specify: garage door
Decorative features:
- 

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: Porte Cochere: Other: concrete lintel
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: parapet

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: new aluminum storm windows cover original; new glass panel doors; sone windows tastefully covered with rock; addition to west end.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7Har6a,6b Date taken: 5/21/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/29/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$44,000


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

1. PROPERTY NAME: Hollis Community Bldg.
2. PROPERTY ADDRESS Street Address: 511 N. Morton
City: Hollis County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: 38-44 Township:
Block or Section: Block 5, Motley Heights Add. Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
- Building: x Object:
Structure: Site:

6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes

9. SITE SETTING AND FEATURES
- Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:



10. HISTORIC USE
- | | | |
|---------------------|-------------|-------------------------|
| Archaeological: | Fine Arts: | Recreation: |
| Agriculture: | Government: | Education: |
| Commercial: | Industrial: | Residential: |
| Community/Public: x | Military: | Exploration/Settlement: |
| Other: | | Religious: |

11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:

15. PRESENT USE
- | | | |
|--------------|------------|----------------------|
| Agriculture: | Industry: | Residential: (type): |
| Commercial: | Military: | Community/Public: |
| Education: | Museum: | Social/Fraternal: x |
| Government: | Religious: | Other: |

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
- | | |
|---|------------|
| Wood Frame: Siding, Historic: | Present: x |
| Masonry, bearing: x Type Brick: Stone: x Type: Native | |
| Other, describe: | |
20. WINDOWS Historic, Wooden: Metal: Present: wood sash
- | | |
|------------------------------------|-------------------|
| Window type Hung: x Single: | Double: x Triple: |
| Transoms Yes: No: x | |
| Casement: Sliding: Fixed: | Pivotal: |
| Hopper: Other: | |
| Special Windows and Configurations | |
| Round: Arch: Bay: Other: | |
| Glazing: Decorative aspects: | |
21. DOORS Material and type. Historic: Present: x
- | | |
|-----------------------|-------------------|
| Style: Wood: x Metal: | Single: x Double: |
| Other, specify: | |
| Decorative features: | |

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: pilasters;
arched and recessed front entry.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include
dates, work done and effect. Continue on additional sheets if needed:
window openings frequently cemented over; new metal sash windows; brick addition
to the northwest end.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important
example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are
NOT acceptable.

Number: 7HAR8a,8b Date taken: 5/21/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/29/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$4,095 + ?


*NOTE. To continue any item, list by item number and title. Attach
additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Will Husband Stadium
2. PROPERTY ADDRESS Street Address: W. Walnut
City: Hollis County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: 7-12 Township:
Block or Section: Block 20, College Heights Add. Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: additional seating added to north end of west stands; new press box on west stands.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR9a,9b Date taken: 5/21/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/29/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$8,896

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Vinson Sch. Home Ec and Shop Bldg.
2. PROPERTY ADDRESS Street Address: East St.
City: Vinson County: Harmon
State: OK Zip Code: 73571 Region: 7
3. PROPERTY LOCATION Lot: all Township:
Block or Section: Block 1, Willis Add. Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP ^{N↑}
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:
- 

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other: stoop

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: beaded mortar; parapets; concrete window sills and capping on parapet; arched and recessed entryway.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: new windows, garage door converted to single door entry with wood inset.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7Har11a,11b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$9,021


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Goodwill School
2. PROPERTY ADDRESS Street Address:
City: Duke (vic) County: Harmon
State: OK Zip Code: 73532 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: NE2 Range: 24W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): private home
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: wood shingle
Roof type Hipped: x Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: wood sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: x Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: end wall/stone
Other: stoop

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR14a,14b Date taken: 5/18/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$13,160


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Goodwill Sch. Bus Garage
2. PROPERTY ADDRESS Street Address:
City: Duke (vic) County: Harmon
State: OK Zip Code: 73532 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: NE2 Range: 24W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): garage
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: x
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify: garage
Decorative features:



22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR15a,15b Date taken: 5/18/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$13,160

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Arnett Sch. Vo. Ed. Bldg.
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: NW8 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP 
- Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built:
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: x Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Metal
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: Panel
Style: Wood: x Metal: Single: x Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: Porte Cochere: Other: arched
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables: center
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: new glass door on south entry; window openings altered with block insets.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR16a,16b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: ?


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Arnett School Bus Garage
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: NW8 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Wood Sash
Window type Hung: x Single: Double: Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: use of
cobblestone to cap parapet.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include
dates, work done and effect. Continue on additional sheets if needed:
garage doors replaced with wood inserts and new windows installed.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important
example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are
NOT acceptable.

Number: 7HAR17a,17b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne

DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: ?


*NOTE. To continue any item, list by item number and title. Attach
additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Arnett School Teacherage
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: NW8 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential: x
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): teacherage
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Wood Sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify: glass panel
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: x Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables: x
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: stone columns supporting pedimented hoods over entries; projecting eaves;

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed: new doors in front; new windows

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR18a,18b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: ?


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Westview Bus Garage and Home Ec Bldg.
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: SW31 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: x Other: Boys Home (vacant)
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Wood Sash
Window type Hung: x Single: x Double: Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: panel Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: buttresses

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: The original rock front is covered with concrete stucco; garage door openings filled with cement; west windows and south door covered with cement.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR19a,19b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne

DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$10,252


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Westview School Gym
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 3N
Block or Section: SW31 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936-37
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: x Other: Boys Home (vacant)
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: Shed: Flat: Gabled:
Other: arched
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features: keystone



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: Porte Cochere: Other: arched
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: Pilasters:
stepped parapet.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include
dates, work done and effect. Continue on additional sheets of needed: all
windows covered with cement; tin addition to south end (original wall intact).

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important
example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are
NOT acceptable.

Number: 7HAR20a,20b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$11,839

*NOTE. To continue any item, list by item number and title. Attach
additional, full sheets if needed.

ADDITIONAL COMMENTS:

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

HARMON COUNTY

(Region 7)

<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1. Grade School✓	310 N. 6th	Hollis	7HAR5a-c
2. County Ag. Ext. Bldg.✓	Main and Lamar	Hollis	7HAR7a,b
3. School Bus Garage✓	Hendrix Street	Vinson	7HAR10a
4. LaCasaa High Sch. Addn and Teacherage✓	T2N, R25W, NW32	Hollis vic	7HAR12a-c
5. LaCasa School Bus✓ Barn	T2N, R25W, NW32	Hollis vic	7HAR13a
6. Ron School✓	T4N, R25W, NE30	Vinson vic	7HAR21a,b
7. Metcalf School✓	T4N, R25W, NW23	Vinson vic	7HAR22a
8. Carl School✓	T6N, R26W, SE28	Vinson vic	7HAR23a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Hollis Grade School
2. PROPERTY ADDRESS Street Address: 310 N. 6th
City: Hollis County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: 10-15 Township:
Block or Section: Block 20, Hollis Original Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: x Type Brick: x Stone: x Type: Native Stone
Other, describe: Concrete block in rear
20. WINDOWS Historic, Wooden: Metal: Present: Metal
Window type Hung: x Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: Metal
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features: Pilasters with Triangular Pediment
- 

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: x Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: New Flat roof replaces original pitched roof; original rock walls replaced with brick; addition to north end of building.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field Survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR5a,5b,5C Date taken: 5/21/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/28/87

Survey Project No: Yes: x Project Name: WPA Survey, III


30. WPA appropriation: \$70,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Harmon Cty. Ag Ex. Bldg.
2. PROPERTY ADDRESS Street Address: N. Main and E. Lamar
City: Hollis County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: 1-3 Township:
Block or Section: Block 16, Hollis Original Range:
4. PROPERTY TYPE (Category) Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP 
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: NO
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: x Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: x Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: composition
Roof type Hipped: x Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: Native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: metal sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: glass Wood: Metal: x Single: x Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe: arched and recessed front entry.

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: new metal sash windows; large addition to west end; new roof style; two south windows covered with wood inserts.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR7a,7b Date taken: 5/21/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/29/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$8,839

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Vinson School Bus Garage
2. PROPERTY ADDRESS Street Address: Hendrix St.
City: Vinson County: Harmon
State: OK Zip Code: 73571 Region: 7
3. PROPERTY LOCATION Lot: 2 Township:
Block or Section: Block 1, Willis Add. Range:
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built:
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): garage
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: garage Wood: x Metal: Single: Double:
Other, specify:
Decorative features:
- East St.
Hendrix St.
X

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: roof gone; middle of structure destroyed by storm.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR10a Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: ?


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: LaCasa High Sch. Add. and Teacherage
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 2N
Block or Section: NW32 Range: 25W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain: x
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: deteriorated
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: Type:
Other, describe: poured concrete
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets of needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR12a,12b Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$32,064.65


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: LaCasa Sch. Bus Garage
2. PROPERTY ADDRESS Street Address:
City: Hollis (vic) County: Harmon
State: OK Zip Code: 73550 Region: 7
3. PROPERTY LOCATION Lot: Township: 2N
Block or Section: NW32 Range: 25W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built:
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: deteriorated
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: x Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: x Type: native
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: deteriorated condition; roof gone, doors gone, windows gone.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR13a Date taken: 5/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 6/30/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation:


*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Ron School
2. PROPERTY ADDRESS Street Address:
City: Vinson (vic) County: Harmon
State: OK Zip Code: 73571 Region: 7
3. PROPERTY LOCATION Lot: Township: 4N
Block or Section: NE30 Range: 25W
4. PROPERTY TYPE (Category) Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP N↑
6. Identification uncertain: x
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built:
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: ruins
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present: x
Masonry, bearing: x Type Brick: Stone: Type: poured concrete
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:



22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR21a,21b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation:

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:


HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Metcalf School
2. PROPERTY ADDRESS Street Address:
City: Vinson (vic) County: Harmon
State: OK Zip Code: 73571 Region: 7
3. PROPERTY LOCATION Lot: Township: 4N
Block or Section: NW23 Range: 25W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: Site:

N↑

6. Identification uncertain: x
7. Unable to locate:
8. Warrant further study National Register: no



9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:

11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor:
12. ORIGINAL SITE Yes: No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:

BUILDING CONSTRUCTION DESCRIPTION

16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7HAR22a Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$5,465

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM

Figure "D"

1. PROPERTY NAME: Carl School and Aud.
2. PROPERTY ADDRESS Street Address:
City: Vinson (vic) County: Harmon
State: OK Zip Code: 73571 Region: 7
3. PROPERTY LOCATION Lot: Township: 6N
Block or Section: SE28 Range: 26W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP N↑
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: no
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: x Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present: tin
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: x Siding, Historic: Present: x
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: Wood Sash
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: panel Wood: x Metal: Single: x Double: x
Other, specify:
Decorative features:
- 

22. LARGE EXTERIOR FEATUR

Tower: projecting: joined: other:
Entries: x Pedimented: Porte Cochere: Other: projecting
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include
dates, work done and effect. Continue on additional sheets if needed:
original roof replaced with tin roof.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important
example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: field survey

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are
NOT acceptable.

Number: 7HAR23a,23b Date taken: 05/20/87 Photographer: Barry Thorne

29. NAME OF PREPARER: Barry Thorne DATE: 07/01/87

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$4,000

*NOTE. To continue any item, list by item number and title. Attach
additional, full sheets if needed.

ADDITIONAL COMMENTS: