

WPA RESOURCES WARRANTING FURTHER STUDY FOR NATIONAL REGISTER

WASHITA COUNTY

(Region 7)

	<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1.	Swimming Pool/Park ✓	2nd and Magnolia	Cordell	7WAS5a-c
2.	Lee Civic Park —	2nd & Glen English	Cordell	7WAS7a-c
3.	Civic Park Bldgs. ✓	3rd & Glen English	Cordell	7WAS8a,b
4.	Dill City School ✓	4th & Rambo	Dill City	7WAS13a-c
5.	Rocky Public School ✓	Main Street	Rockey	7WAS16a,b
6.	Public School —	7th and Washington	Sentinel	7WAS20a,b
7.	Cloud Chief School ✓	T9N, R15W, SW13	Gotebo vic	7WAS2a,b

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell City Pool and Park
2. PROPERTY ADDRESS Street Address: 2nd & N. Magnolia Streets
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 1-12 Township: 9N
Block or Section: Block 12, College Addition Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: x Sliding: Fixed: Pivotal: x
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Wrought iron grills have been mounted over all windows.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS5a-5c Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: A small park has been created on the site where the old pump house is located and it is surrounded by a stone wall. This feature is represented by photo # 7WAS5c.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Lee Civic Park
2. PROPERTY ADDRESS Street Address: E. 2nd & N. Glenn English Street
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 1-24 Township: 9N
Block or Section: Block 30, Original Townsite Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 6WAS7a-7c Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,051

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Photographs of sample structures include a drinking fountain, creek and bridge, and a barbeque pit.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell Civic Park Buildings
2. PROPERTY ADDRESS Street Address: E. 3rd & N. Glenn English Streets
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 7-12 Township: 9N
Block or Section: Block 27 Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal:
Government: Religious: Other: Recreation
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Front door is not WPA original equipment; all windows are post-WPA.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS8a,8b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$36,135

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: This portion of Civic Park is adjacent to the larger park area. In this portion of the park, the original Park Office building was built. Today that building is used as the "Scout Hut".

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Dill City Public School
2. PROPERTY ADDRESS Street Address: 4th & Rambo Streets
City: Dill City County: Washita
State: OK Zip Code: 73641 Region: 7
3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 5SW Range: 18W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Metal Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Window glass has been opaqued with paint 2/3 of their length; all windows are aluminum.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS13a-13c Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$27,236

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The gymnasium that appears in the photographs was not a part of this project.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Rocky Public School
2. PROPERTY ADDRESS Street Address: Main Street
City: Rocky County: Washita
State: OK Zip Code: 73661 Region: 7
3. PROPERTY LOCATION Lot: Township: 8N
Block or Section: Section 24NW Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: x Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public: x
Education: Museum: Social/Fraternal: x
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projected: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows are boarded; the door on the north side is not an original feature; the original opening has been boarded to accomodate a single door. The lean-to on the north side is not a part of the original project.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS16a,16b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$40,674

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: None of the alterations are so great that historical integrity cannot be restored.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Sentinel Public School
2. PROPERTY ADDRESS Street Address: 7th & Washington Streets
City: Sentinel County: Washita
State: OK Zip Code: 73661 Region: 7
3. PROPERTY LOCATION Lot: 7-9 Township: 8N
Block or Section: Block 26, First Addition Range: 19W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1938
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No: x
Casement: Sliding: Fixed: Pivotal: -
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projected joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Stairs on east side are not original equipment; brick in the front is not original construction; the covered entrance in the front is not a part of the original project.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report and Joe Schwarz, Maintenance.

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS20a,20b Date taken: June 4, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$45,500

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS:

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cloud Chief Public School
2. PROPERTY ADDRESS Street Address: Section 13SW; 9N; 15W
City: Gotebo (vic) County: Washita
State: OK Zip Code: 73041 Region: 7
3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 13SW Range: 15W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: Yes
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1937-38
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: x Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATUR

Tower: projecti joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Cement-block ante-room on the East end is not an original feature. A large opening was made in the wall of the gymnasium.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS2a-2c Date taken: June 2, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$42,748

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The only building that warrants further study is the main school building. The alterations and defacing done to the gymnasium compromises the historical integrity of that building.

INVENTORY OF WPA RESOURCES NOT SUITABLE FOR NATIONAL REGISTER

WASHITA COUNTY

(Region 7)

<u>Property Name</u>	<u>Location</u>	<u>Town</u>	<u>Photo Ref.</u>
1. Canute School ✓	NE23, T10N, R20W	Canute	7WAS1a
2. City Hall -	101 E. Main	Cordell	7WAS3a,b
3. Fire and Police Dept. ✓	117 E. Clay	Cordell	7WAS4a,b
4. School Addition ✓	3rd and Magnolia	Cordell	7WAS9a-c
5. School Ag. Bldgs. ✓	3rd and Magnolia	Cordell	7WAS10a,b
6. County Jail ✓	Main and 1st	Cordell	7WAS11a,b
7. Water Pump Bldg. ✓	Broadway	Dill City	7WAS12a,b
8. Community Bldg. ✓	3rd and Main	Sentinel	7WAS19a,b
9. Lake Valley Sch. ✓	T8N, R16W, NW14	Gotebo vic	7WAS15a-d
10. Cowden Sch. Aud/Gym ✓	T9N, R14W, SW17	C'dell vic	7WAS12a,b
11. Port School -	T9N, R20W, SE35	Sent'l vic	7WAS17a-e
12. Port Teacherages ✓	T9N, R20W, SE35	Sent'l vic	7WAS18a-c

also:

Cordell Water Tower College Street Cordell 7WAS11a

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Canute School
2. PROPERTY ADDRESS Street Address: Section 23NE;10N;20W
City: Canute County: Washita
State: OK Zip Code: 73626 Region: 7
3. PROPERTY LOCATION Lot: Township: 10N
Block or Section: Section 23NE Range: 20W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate: x
8. Warrant further study National Register:
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Not in use
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: Full: Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: Concrete: x Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: Present:
Masonry, bearing: Type Brick: Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projecting: joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS1a Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$25,749

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The only remaining part of this structure is the foundation, therefore it does not qualify for further study.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell City Hall
2. PROPERTY ADDRESS Street Address: 101 E. Main Street
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 13 Township: 10N
Block or Section: Block 46, Original Townsite Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Single: Double: Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Metal Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: All windows and doors are added equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS3a,3b Date taken: June 4, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$17,275

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: It is apparent that this project was a renovation and not an initial construction project. Therefore, this rproperty does not warrant further study as historical integrity has been compromised.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell Fire and Police Departments
2. PROPERTY ADDRESS Street Address: 117 E. Clay
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 19 & 20 Township: 10N
Block or Section: Block 54, Original Townsite Range: 17W 2
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 2 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present: x
Window type Hung: Metal Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Glass Panel Wood: x Metal: Single: x Double:
Other, specify: Metal Overhead
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projecting. joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
The wings are added features to the original building; all doors and windows are added equipment.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS4a,4b Date taken: June 4, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: \$12,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The building has been enlarged by the addition of two wings and these features compromise the historical integrity.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell School Addition
2. PROPERTY ADDRESS Street Address: E.3rd & N. Magnolia
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: Not numbered Township: 9N
Block or Section: Block: City Tract Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1941
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: x
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All window openings have been boarded up; East entrance has been altered to accomodate a single entry door; the gabled addition at the top is an added feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS9a,9b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$11,950

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The alterations to the building have not been so drastic as to compromise the historical integrity of the structure.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cordell School Agricultural Buildings
2. PROPERTY ADDRESS Street Address: E. 3rd & N. Magnolia Streets
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: not numbered Township: 9N
Block or Section: Block:City Tract Range: 17W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: x Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: x Museum: Social/Fraternal:
Government: Religious: Other: School Bus Storage
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Metal Single: Double: x Triple:
Transoms Yes: x No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Glass panel Wood: x Metal: Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: x placement/material: Exposed metal
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
Opening on East wall was altered to accomodate a single door. A large door was added to accomodate bus entry.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS10a,10b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey,III

30. WPA appropriation: \$8,839

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The massive alterations have compromised the historical integrity of this structure.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Washita County Jail
2. PROPERTY ADDRESS Street Address: Main Street, at the Court House
City: Cordell County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: 17 & 18 Township: 9N *17W*
Block or Section: Block 40, Original Townsite Range: *348W*
4. PROPERTY TYPE (Category) *SVB* 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: x Good: Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: J.I.Davis, architect Year Built: 1939
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 3 Full: 2 Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: Type: Stucco
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Metal Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE
Tower: projectir joined: other:
Entries: Pedimented: Porte Cochere: x Other:
Porches: x Entry: Full Width: x Wrap-around: Other: Stoop
Stairs: x Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
The porte cochere does seem to be an original feature. All doors are aluminum framed glass doors; all windows are combination storm and screens.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS11a,11b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$21,062

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: If, indeed, the porte cochere is not a part of the original construction project, the historical integrity has been compromised because of its addition.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Water Pump Building
2. PROPERTY ADDRESS Street Address: Broadway
City: Dill City County: Washita
State: OK Zip Code: 73641 Region: 7
3. PROPERTY LOCATION Lot: 14-16 Township: 9N
Block or Section: Block 54, Original Townsite Range: 18W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: Object:
Structure: x Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area: x
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: x Education:
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: x Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other: Abandoned
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: No Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows and doors have been boarded.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS14a,14b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$12,243

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: All that remains of this project is the pump house proper. The tower has been long removed.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Sentinel Community Building
2. PROPERTY ADDRESS Street Address: 3rd & Main
City: Sentinel County: Washita
State: OK Zip Code: 73664 Region: 7
3. PROPERTY LOCATION Lot: 8 Township: 8N
Block or Section: Block 10, Original Townsite Range: 23NE
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: Commercial area:
Residential: Scattered Buildings:
Mixed use: x Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation: x
Agriculture: Government: Education:
Commercial: Industrial: Residential:
Community/Public: x Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: x Fair: Poor:
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1936
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: x Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: x Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: x Double: x
Other, specify: Overhead
Decorative features:

22. LARGE EXTERIOR FEATURES
Tower: projecting joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
All windows have been boarded and the overhead doors are an added feature.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS19a,19b Date taken: June 3, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$16,000

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Massive alterations have discredited the historical integrity of this building.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Lake Valley School
2. PROPERTY ADDRESS Street Address: Section 14NW; 8N; 16W
City: Gotebo (vic) County: Washita
State: OK Zip Code: 73041 Region: 7
3. PROPERTY LOCATION Lot: Township: 8N
Block or Section: Section 14NW Range: 16W
4. PROPERTY TYPE (Category) 5. PLACEMENT ON BLOCK or MAP
Building: x Object:
Structure: Site:
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: Sandstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Metal Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: x Metal: Single: Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectin_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: x Full Width: Wrap-around: Other: Stoop
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:
The portion of the school that contained the classrooms has been altered into a private residence, and what material that was not used was scraped and removed.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS15a-15d Date taken: June 2, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$47,705

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Historical integrity is no longer evident because of the massive renovations made to both the classroom portion of the school and the out lying building that was originally the bus garage and shop.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Cowden School Auditorium/Gymnasium
2. PROPERTY ADDRESS Street Address: Section 17SW;9N;14W
City: Cordell (vic) County: Washita
State: OK Zip Code: 73632 Region: 7
3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 17SW Range: 14W
4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: 1935
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: (type):
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other: Abandoned
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled:
Other: Barrel
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: Metal: x Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: x Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: x Present:
Style: Wood: x Metal: Single: x Double: x
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURES

Tower: projectile joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed: All doors are boarded against trespassers; lean-to on the North side is addition.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS12a,12b Date taken: June 2, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$13,636

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: Historical integrity is compromised because each of the exterior walls have had some damage and/or alteration done to them.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Port School
2. PROPERTY ADDRESS Street Address: Section 35SE; 9N; 20W
City: Sentinel (vic) County: Washita
State: OK Zip Code: 73664 Region: 7
3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 35SE Range: 20W
4. PROPERTY TYPE (Category)
Building: x Object:
Structure: x Site:
5. PLACEMENT ON BLOCK or MAP
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings:
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Joe I. Davis, architect Year Built: 1938-1940
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: Partial: Below Ground: 1
17. FOUNDATION TYPE Stone: x Brick: Concrete: Other:
18. ROOFING MATERIAL Historic: Present:
Roof type Hipped: Shed: Flat: Gabled:
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: Stone: x Type: andstone
Other, describe:
20. WINDOWS Historic, Wooden: Metal: Present:
Window type Hung: Single: Double: Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present:
Style: Wood: Metal: Single: Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower: projectir_ joined: other:
Entries: Pedimented: Porte Cochere: Other:
Porches: Entry: Full Width: Wrap-around: Other:
Stairs: Balconies: Dormers: Gables:
Verandas: Chimneys: placement/material:
Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS17a-17e Date taken: June 4, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: \$132,163

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The main school building is in ruins and it is impossible to determine what the architectural features were. The storm cellar and wall are in fair condition. The storm cellar has been altered both exteriorally as well as in the interior. The tennis courts which were situated on the roof of the storm cellar are no longer present.

HISTORIC PRESERVATION SURVEY INVENTORY FORM:

Figure "D":

1. PROPERTY NAME: Port School Teacherages
2. PROPERTY ADDRESS Street Address: Section 35SE; 9N; 20W
City: Sentinel (vic) County: Washita
State: OK Zip Code: 73664 Region: 7
3. PROPERTY LOCATION Lot: Township: 9N
Block or Section: Section 35SE Range: 20W
4. PROPERTY TYPE (Category)
Building: x Object:
Structure: Site:
5. PLACEMENT ON BLOCK or MAP
6. Identification uncertain:
7. Unable to locate:
8. Warrant further study National Register: No
9. SITE SETTING AND FEATURES
Open Land: x Commercial area:
Residential: Scattered Buildings: x
Mixed use: Industrial:
Other:
10. HISTORIC USE
Archaeological: Fine Arts: Recreation:
Agriculture: Government: Education: x
Commercial: Industrial: Residential:
Community/Public: Military: Exploration/Settlement:
Other: Religious:
11. CONDITION OF RESOURCE Excellent: Good: Fair: Poor: x
12. ORIGINAL SITE Yes: x No: Date moved and from where:
13. ARCHITECT/BUILDER: Year Built: unknown
14. ACCESSIBLE Yes: x No:
15. PRESENT USE
Agriculture: Industry: Residential: x (type): Private
Commercial: Military: Community/Public:
Education: Museum: Social/Fraternal:
Government: Religious: Other:
- BUILDING CONSTRUCTION DESCRIPTION
16. NUMBER OF STORIES: 1 Full: x Partial: Below Ground:
17. FOUNDATION TYPE Stone: Brick: x Concrete: Other:
18. ROOFING MATERIAL Historic: Present: Composition
Roof type Hipped: Shed: Flat: Gabled: x
Other:
19. WALL CONSTRUCTION
Wood Frame: Siding, Historic: x Present:
Masonry, bearing: x Type Brick: x Stone: Type:
Other, describe:
20. WINDOWS Historic, Wooden: x Metal: Present:
Window type Hung: x Single: Double: x Triple:
Transoms Yes: No:
Casement: Sliding: Fixed: Pivotal:
Hopper: Other:
Special Windows and Configurations
Round: Arch: Bay: Other:
Glazing: Decorative aspects:
21. DOORS Material and type. Historic: Present: x
Style: Wood: Metal: x Single: x Double:
Other, specify:
Decorative features:

22. LARGE EXTERIOR FEATURE

Tower:	projecting	joined:	other:
Entries:	Pedimented:	Porte Cochere:	Other:
Porches: x	Entry: x	Full Width:	Wrap-around: Other:
Stairs:	Balconies:	Dormers: x	Gables:
Verandas:	Chimneys: x	placement/material:	Free standing brick
Other:			

Tower: projectir joined: other:
 Entries: Pedimented: Porte Cochere: Other:
 Porches: x Entry: x Full Width: Wrap-around: Other:
 Stairs: Balconies: Dormers: x Gables:
 Verandas: Chimneys: x placement/material: Free standing brick
 Other:

23. DECORATIVE DETAILS AND/OR MOULDINGS ON EXTERIOR. Describe:

24. UNATTACHED, SMALL OUTBUILDINGS

Vehicle Storage; type:
Work: Storage sheds, matches primary building Yes: No:
Other:

25. DESCRIPTION OF ALTERATIONS OR ADDITIONS TO HISTORIC PROPERTY. Include dates, work done and effect. Continue on additional sheets if needed:

Door on the south side is an addition. The structure was originally a duplex but is now a single family dwelling.

26. INTERIOR FIXTURES AND FINISHES. Built in and remaining.

Lighting fixtures: type:
Ceiling finishes: Floors:
Walls:
Decorative features Staircases: Mantles: Pantries: Cabinets:
Other:

27. SIGNIFICANCE. Association with person, event or period. Important example of style or type of architecture within area:

28. DOCUMENTATION

Sources of information: Field survey report

Photographs. MUST BE CLEAR B&W PRINTS. Polaroid and Color Prints are NOT acceptable.

Number: 7WAS18a-18c Date taken: June 4, 1987 Photographer: Hallberg

29. NAME OF PREPARER: Sharon Hallberg DATE: July 10, 1987

Survey Project No: Yes: x Project Name: WPA Survey, III

30. WPA appropriation: unknown

*NOTE. To continue any item, list by item number and title. Attach additional, full sheets if needed.

ADDITIONAL COMMENTS: The only structure still remaining was the Superintendent's residence according to the present owner, Seabern Young. The changes he has made to the property disqualifies the site for further study.

HISTORIC PRESERVATION SURVEY FORM
(Type or Print clearly)Date Prepared: 6/4/87
Region: 7
Amt. Allocated: \$18,036

#167

1. PROPERTY NAME Historic: Cooling Tower*

Common: ~~#1~~ Cordell Water Tower

2. PROPERTY ADDRESS Street address: N. College St.

City: ~~Washita~~ Cordell

County: Washita

State/Zip Code: OK 73632

3. LEGAL DESCRIPTION Lot: 9-11

Block or Section: #45 - orig townsite

Township: 10N

Range: 17W

4. OWNER'S NAME: City of Cordell

OWNER'S ADDRESS:

5. CATEGORY

Building: ☒Structure: ☒

Object:

Site:

District:

Thematic:

Multiple Resource:

6. PLACEMENT ON

BLOCK &/OR MAP

AREA:

7. SITE SURVEY AND OTHER FEATURES

Open Land:

Woodland:

Scattered Buildings:

Densely Built-up: ☒Commercial: ☒

Industrial:

Residential:

Other:

8. SIGNIFICANCE

Archeology-Prehistoric:

Archeology-Historic:

Agriculture:

Education:

Engineering:

Exploration-

Settlement:

Music:

Philosophy:

Politic/Government:

Architecture:

Religion:

Art:

Commerce:

Communications:

Industry:

Invention:

Landscape

Architecture:

Science:

Social/Humanitarian: ☒

Theater:

Community Planning:

Conservation:

Economics:

Law:

Literature:

Transportation:

Military:

Other:

9. CONDITION OF SITE

Excellent: ☒

Fair:

Good:

Ruins:

Deteriorated:

10. ORIGINAL SITE Yes: ☒
No, Date Moved:

11. ARCHITECT(S)/BUILDER(S):

YEAR BUILT: 10/36

PRESENT USE:

Agriculture:

Commercial:

Educational:

Entertainment:

Government: ☒

Industrial:

Military:

Museum:

Park:

Private Residence:

Religious:

Scientific:

Transportation:

District, mixed

Specify:

(Complete items 13-26 only for Buildings)

12. ACCESSIBLE Yes: ☒ No:

13. NUMBERS OF STORIES:

14. BUILDING MATERIAL

15. STRUCTURAL SYSTEM

Clapboard: Brick:
Sandstone: Stucco:
Stone: Board & Batten:
Shingle Siding: Other:

Wood frame w/
interlocking joints:
Wood frame w/ light
members:

Masonry load bearing
walls:

Metal (explain:)
Other:

16. FOUNDATION MATERIALS

Natural Stone:
Reinforced Concrete:
Log:
Brick:

17. ROOF MATERIALS

Tile: Spanish Tile:
Shingle: Slate:
a. Wood: Built-up:
b. Composition:
Metal (Explain):

18. ROOF SHAPE

19. CHIMNEYS

Gabled: Gambrel:
Hipped: Stepped Gable:
Shed: Conical:
Flat

Free Standing: Concrete:
End Wall: Exposed
Natural Stone: Metal:
Brick: Stucco:
Adobe:

20. WINDOWS

Double-Hung: Transom:
Casement: Clerestory:
Triple-Hung: Bay:
Sliding: Metal Sash:
Fixed: Wood Sash:

Palladian: Stained Glass:
Oval: Beveled Glass:
Round: Etched Glass:
Gothic: Lead Glass:
Romanesque:

21. DORMERS

22. DOORS

Gabled: Wood: specify: Transom:
Wall: Metal: Single:
Shed: Glass Panel: Double:
Sidelights: Overhead:

23. OUTBUILDINGS

24. PORCHES AND OTHER PROJECTIONS

Barns: Shed:
Carriage House: Greenhouse:

Portico: Monumental:
Veranda: Carriage Porch/
Porte-Cochere:

Garage: Landscape Features:
Privy:
Other:

Stoop:
Single: Attached Sheds:
Double: Other (explain):

25. DESCRIBE ALTERATIONS, ADDITIONS (i.e. dates, specifies, before and after appearance:

26. ORIGINAL EQUIPMENT

Brass Fixtures: Marble: Dirt: Suspended: Gypboard:
Gas Lights: Tile: CEILINGS: Coffered: Wooden:
FLOOR MATERIALS: Brick: Tin: Beaded: Other:
Wood: Concrete: Vaulted: Plaster:

27. STATEMENT OF SIGNIFICANCE (attach other sheets if necessary):

28. SOURCES OF INFORMATION:

29. ATTACH A B&W PHOTOGRAPH OR COLOR SLIDE (Polaroid not acceptable):

30. NAME OF PREPARER:

7 WAS 11a

(For items requiring narrative answers, list them by number below and continue the narrative.)